



MANDATORY
SERVICE BULLETIN

No. 0003

DATE: 20TH August 2010

**58 KEMP STREET
KILBIRNIE, WELLINGTON 6022, NZ**

- SUBJECT:** Defective turn buckle barrels p/n **W4A1501-8606B**
- MODELS AFFECTED:** All aircraft with batch number 11904 barrels fitted.
- COMPLIANCE TIME:** This Service Bulletin becomes effective upon receipt at which time compliance must be met.
- BACKGROUND:** The Vintage Aviator have found one batch of turnbuckle barrels which were manufactured incorrectly, and have defective threads.
- COMPLIANCE:** Remove all barrels with batch number 11904, and replace with batch number 12661 or later, then destroy all defective barrels to ensure full compliance with this service bulletin.
- PARTS SUPPLIER:** The Vintage Aviator Ltd.
- ADDITIONAL INFORMATION:** Photo showing cutaway view of defective threads.

